

Oil Field Environmental Incident Summary

Incident: 20141221161513 **Date/Time of Notice:** 12/21/2014 16:15

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: Parshall 53-1014H

Field Name: PARSHALL

Well File #:

Date Incident: 12/21/2014 **Time Incident:** 02:45

Facility ID Number: 227115-01

County: MOUNTRAIL

Twp: 152

Rng: 90

Sec: 10

Qtr: NW NW

Location Description:

Submitted By: Danielle Dupay

Received By:

Contact Person: Danielle Dupay
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	3	Barrels	3	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

N/A

Areal Extent:

N/A

Potential Environmental Impacts:

N/A

Action Taken or Planned:

All liquids were contained inside lined water battery berm. Liquids were removed by vac truck and solid material will be removed and disposed of.

Wastes Disposal Location: Liquids at SWD, Solids will be disposed of at Clean Harbors

Agencies Involved:

Updates

Date: 12/22/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to valve/piping connection leak, remained on location within the diking according to the report. NDIC retains oversight.